



Vocality International Ltd Lydling Barn Lydling Farm Puttenham Lane Shackleford Surrey GU8 6AP UK
 Tel: +44 1483 813 120 Web: www.vocality.com Emails: sales@vocality.com

Declaration of Conformity

Document Number DoC-V150/16/02

We Vocality International Ltd at the above address declare under our sole responsibility that the product detailed below to which this declaration relates complies with protection requirements of the following EU Directives:

- Low Voltage Directive 2006/95/EC
- The Electromagnetic Compatibility Directive 2004/108/EC
- The RoHS2 Directive 2011/65/EU



Equipment description **Multiplexer/Router**

Make/Brand **Vocality International Ltd**

V150 (68150 chassis, 68151 standard CPU option, 68153 FXS option, 68154 Ethernet option, 68154/PoE Ethernet option, 68164 Radio Relay E&M 4-wire option, 68155 Digital Voice card ISDN E1/T1 PRI (24/30 channels), 68155/DUAL Dual Digital Voice card ISDN E1/T1 PRI (48/60 channels), 68156 FXO option, 68201 High speed CPU option, 68204 High speed serial quad data option, 68205 High speed serial quad data 8 port expansion option)

Model Numbers

This equipment complies with the following harmonised European Standards:

- EN60950-1:2006+A2:2013 Information technology equipment. Safety. General requirements
- BS EN 61000-6-3:2007 Electromagnetic compatibility (EMC). Generic standards. Emission standard for residential, commercial and light-industrial environments
- BS EN 61000-6-1:2007 Electromagnetic compatibility (EMC). Generic standards. Immunity for residential, commercial and light-industrial environments

A technical file for this equipment is retained at the above address

This Declaration of Conformity was prepared according to EN ISO/IEC 17050-1:2004.

	Signature of responsible person *
J Curnyn	Name of responsible person*
Chief Technical Officer	Position of responsible person*
Shackleford, April 2016	Place and Date of Issue

* being the person authorised to sign on behalf of the manufacturer



Vocality International Ltd Lydling Barn Lydling Farm Puttenham Lane Shackleford Surrey GU8 6AP UK
 Tel: +44 1483 813 120 Web: www.vocality.com Emails: sales@vocality.com

FCC Declaration of Conformity

Document Number DoC-V150/16/02/FCC

We Vocality International Ltd at the above address declare under our sole responsibility that the product detailed below to which this declaration relates complies with Part 15 of the following FCC Rules:


Equipment description **Multiplexer/Router**
 Make/Brand **Vocality International Ltd**
V150 (68150 chassis, 68151 standard CPU option, 68153 FXS option, 68154 Ethernet option, 68154/PoE Ethernet option, 68164 Radio Relay E&M 4-wire option, 68155 Digital Voice card ISDN E1/T1 PRI (24/30 channels), 68155/DUAL Dual Digital Voice card ISDN E1/T1 PRI (48/60 channels), 68156 FXO option, 68201 High speed CPU option, 68204 High speed serial quad data option, 68205 High speed serial quad data 8 port expansion option)
 Model Numbers

OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS:

1. This device may not cause harmful interference and
2. This device must accept any interference received, including interference that may cause undesired operation.

NOTE This equipment has been tested and found to comply with the limits for a class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- a. Reorient or relocate the receiving antenna.
- b. Increase the separation between the equipment and the receiver.
- c. Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- d. Consult the dealer or an experienced radio technician for help.

	Signature of responsible person *
J Curnyn	Name of responsible person*
Chief Technical Officer	Position of responsible person*
Shackleford, April 2016	Place and Date of Issue

** being the person authorised to sign on behalf of the manufacturer*